

Jonathan Kammerer Plant Manger

Americas Styrenics LLC 17401 State Route 7 South Marietta, Ohio 45750

Phone: 740-760-0744

February 5, 2018

7010 FED -8 PM 12: 04

Mr. Scott Bergreen, Supervisor Ohio EPA Southeast District Office Division of Environmental Response and Revitalization 2195 Front Street Logan, OH 43138-8637

Re: Response to RCRA Corrective Action Request

Americas Styrenics, LLC – OHD000608646; Marietta, Ohio, Washington County, 45750

Dear Mr. Bergreen:

Americas Styrenics, LLC — Marietta Facility is submitting this letter in response to the OEPA letter dated August 29, 2017 which requested an update on RCRA Corrective Actions (CA) at the Marietta site. Union Carbide Corporation is managing the only active remediaton projects at the Marietta site under the CERCLA program. Based on available information, Americas Styrenics developed the attached table to provide a status update on previously idenitified solid waste management units (SWMU) at the Marietta site.

If you have any questions about this information, feel free to contact Doug Currey, AmSty Marietta facility, at 740-760-0652 or David Thomas, AmSty Corporate office, at 832-616-7946.

Sincerely

Jonathan Kammerer

Cc: Doug Currey, David Thomas, Joe Hulett

Original SWMU list based on 1989 USEPA Visual Site inspection Report

| SWMU | DESCRIPTION | STATUS (2017) |
|---------|-------------------------------------|-------------------------------|
| #1 | Vertical Liquid Waste Incinerator | Closed |
| #2 | Horizontal Liquid Waste Incinerator | Closed |
| #3 | North Tank Farm Drum Storage Area | Closed |
| #4 | Loading Dock Drum Storage Area | NFA |
| #5 | New Drum Storage Area | Closed |
| #6 | Lab Waste Storage Area | NFA |
| #7 | Molten Salt Bath | Closed |
| #8 | Old Surface Impoundment | UCC |
| #9, #10 | Tanks 204 and 107 | NFA |
| 11 | Wastewater Conveyance System | No evidence of release - NFA |
| 12 | Tank 2108 | Sampling completed - NFA |
| 13 | Used Oil Tank | Closed |
| 14 | Scrap Area | Closed |
| 15 | Contaminated Soil Storage | Material removed and sent for |
| 16 | Soft Polymer Collection Drums | offsite disposal – NFA NFA |
| 17 | Maintenance Area Used Oil | NFA |
| 18 | Lab Area Used Oil Accumulation Area | NFA |
| 19 | Stormwater Conveyance Ditches | Closed |
| 20 | Waste Syrup Collection Drum | NFA |
| 21 | Spray Pond | UCC |
| | | |

Status Codes:

NFA – No further action based on results from soil sampling or visual site inspection.

UCC – area managed by Union Carbide (UCC) or ownership of property was transferred to UCC.